

- U0001 - Controller Area Network (CAN) Bus Communication (ECM)
- U1000 - Class 2 Communication Malfunction
- U1001~U1254 - Loss of XXX Communications
- U1002~U1015 - Loss of serial communications for class 2 devices
- U1016 - Loss of Class 2 Communication with VCM
- U1016 - Loss of Communications with PCM
- U1017~U1025 - Loss of serial communications for class 2 devices
- U1026 - Loss of ATC Class 2 Communication
- U1027~U1039 - Loss of Serial Communications for Class 2 Devices
- U1040 - Loss of Class 2 Communications with ABS
- U1041 - Loss of EBCM Communication
- U1042 - Lost Communications with Brake/Traction Control System
- U1043~U1055 - Loss of Serial Communications for Class 2 Devices
- U1056 - Loss of Communications with RSS
- U1057~U1060 - Loss of Serial Communications for Class 2 Devices
- U1161 - Loss of PDM Serial Data
- U1062 - Loss of Serial Communications for Class 2 Devices
- U1163 - Loss of RRDM Serial Data
- U1064 - Loss of Communications with DIM
- U1065 - Loss of Communications with IPM
- U1066 - Loss of Communications with RIM
- U1067~U1069 - Loss of Serial Communications for Class 2 Devices
- U1170 - Loss of Driver Door Switch Asm Serial Data
- U1071~U1087 - Loss of Serial Communications for Class 2 Devices
- U1088 - Loss of Communications with SDM
- U1089~U1095 - Loss of Serial Communications for Class 2 Devices
- U1096 - Loss of Communications with IPC
- U1097~U1127 - Loss of serial communications for class 2 devices
- U1128 - Loss of Communications with IRC
- U1129 - Loss of Communications with AMP
- U1130~U1143 - Loss of serial communications for class 2 devices
- U1144 - Loss of Communications with PHN
- U1145 - Loss Of NAV Communications
- U1146 - Loss Of Onstar Communication
- U1147~U1151 - Loss of serial communications for class 2 devices
- U1152 - Loss Of ACM Serial Data Communication
- U1152 - Loss of Data HCM
- U1153 - Loss of Communications with CCP
- U1154~U1159 - Loss of serial communications for class 2 devices
- U1160 - Loss of Communications with DDM
- U1161 - Loss of PASS Door Module SBI
- U1162 - Loss of Rear Driver Door Module SBI
- U1163 - Loss of Rear PASS Door Module SBI
- U1164 - Loss Of DIM Serial Data Communication
- U1165 - Loss of serial communications for class 2 devices
- U1166 - Loss of Communications with SCM

- U1167 - Loss of serial communications for class 2 devices
- U1168 - Loss Of TTM Communications
- U1169 - Loss of Communications with MMM
- U1170 - Loss of Driver Door Switch SBI
- U1171~U1175 - Loss of serial communications for class 2 devices
- U1176 - Loss Of RFA Communications
- U1177~U1191 - Loss of serial communications for class 2 devices
- U1192 - Loss of VTD Class 2 Serial Data Com
- U1193 - Loss of VIM Class 2 Communication
- U1194~U1254 - Loss of serial communications for class 2 devices
- U1255 - Class 2 Communication Malfunction (Serial Data Line Malfunction)
- U1300 - Class 2 Short to Ground
- U1301 - Class 2 Short to Battery
- U1304 - Loss Of UART Communications
- U1305 - Class 2 Data Link Low or High
- U1500 - Inter-Device Dedicated Bus Malfunction
- U1713 - Loss of Front Door Module to Window Motor High Speed Comm.
- U1715 - Loss of Front Door Module to Window Motor High Speed Comm.
- U1714 - Loss of Front Door Module to Window Motor Normal Speed Comm.
- U1716 - Loss of Front Door Module to Window Motor Normal Speed Comm.
- U1800 - Controller Area Network (CAN) Bus Communication
- U2000 - Invalid BFC Transmitted SPI Data
- U2001 - Invalid IPC Transmitted SPI Data
- U2002 - SPI Data-In Low
- U2003 - SPI Data-In High
- U2004 - SPI Data-Out Low
- U2005 - SPI Data-Out High
- U2006 - SPI Clock-Out Low
- U2007 - SPI Clock-Out High
- U2050 - SIR PPS/CPS Communications Link malfunction
- U2100 - Controller Area Network (CAN) Bus OFF
- U2100 - CAN-BUS Communication Malfunction
- U2102 - More Controllers on Bus than Programmed
- U2103 - Fewer Controllers On Bus Than Programmed
- U2104 - CAN Bus Reset Counter Overrun
- U2105 - CAN Bus Error ECM
- U2105 - Lost Comm with Engine Control System
- U2106 - Lost Comm with Trans Control System
- U2107 - Lost Communications with Body Control System
- U2108 - CAN Bus Error ABS
- U2108 - Lost Comm with ABS Control System
- U2150 - Navigation ECU Gateway Communication Error
- U2151 - Navigation ECU Communication Malfunction
- U2153 - VICS ECU Communication Error